

**3**

# **FUNDAMENTALS OF MACHINE DESIGN**

---

**P. ORLOV**



\* S K N 0 0 1 2 2 3 \*

# **FUNDAMENTALS OF MACHINE DESIGN**

**P. ORLOV**

TRANSLATED FROM THE RUSSIAN

by A. TROITSKY



THƯ VIỆN TRƯỜNG ĐHSPKT

SKN 001223




MIR PUBLISHERS • MOSCOW

## Contents

<b>Chapter 1.</b>	<b>Assembly . . . . .</b>	<b>9</b>
1.1.	Axial and Radial Assembly . . . . .	11
1.2.	Independent Disassembly . . . . .	21
1.3.	Successive Assembly . . . . .	22
1.4.	Withdrawal Facilities . . . . .	25
1.5.	Dismantling of Flanges . . . . .	28
1.6.	Assembly Locations . . . . .	29
1.7.	Prevention of Wrong Assembly . . . . .	30
1.8.	Access of Assembly Tools . . . . .	34
1.9.	Rigging Devices . . . . .	36
1.10.	Spur Gear Drives . . . . .	37
1.11.	Bevel Gear Drives . . . . .	41
1.12.	Spur-and-Bevel Gear Drives . . . . .	46
<b>Chapter 2.</b>	<b>Convenience in Maintenance and Operation . . . . .</b>	<b>48</b>
2.1.	Facilitating Assembly and Disassembly . . . . .	48
2.2.	Protection Against Damage . . . . .	54
2.3.	Interlocking Devices . . . . .	56
2.4.	External Appearance and Finish of Machines . . . . .	57
<b>Chapter 3.</b>	<b>Designing Cast Members . . . . .</b>	<b>60</b>
3.1.	Wall Thickness and Strength of Castings . . . . .	61
3.2.	Moulding . . . . .	63
3.3.	Simplification of Casting Shapes . . . . .	78
3.4.	Separation of Castings into Parts . . . . .	78
3.5.	Moulding Drafts . . . . .	80
3.6.	Shrinkage . . . . .	82
3.7.	Internal Stresses . . . . .	83
3.8.	Simultaneous Solidification . . . . .	85
3.9.	Directional Solidification . . . . .	87
3.10.	Design Rules . . . . .	87
3.11.	Casting and Machining Locations . . . . .	101
3.12.	Variations in Casting Dimensions and Their Effect on the Design of Castings . . . . .	102
3.13.	Dimensioning . . . . .	109
<b>Chapter 4.</b>	<b>Design of Parts to Be Machined . . . . .</b>	<b>112</b>
4.1.	Cutting Down the Amount of Machining . . . . .	114
4.2.	Press Forging and Forming . . . . .	117
4.3.	Composite Structures . . . . .	119
4.4.	Elimination of Superfluously Accurate Machining . . . . .	121

4.5.	Through-Pass Machining . . . . .	123
4.6.	Overtravel of Cutting Tools . . . . .	127
4.7.	Approach of Cutting Tools . . . . .	132
4.8.	Separation of Surfaces to Be Machined to Different Accuracies and Finishes . . . . .	136
4.9.	Making the Shape of Parts Conformable to Machining Conditions . . . . .	140
4.10.	Separation of Rough Surfaces from Surfaces to Be Machined . . . . .	144
4.11.	Machining in a Single Setting . . . . .	144
4.12.	Joint Machining of Assembled Parts . . . . .	146
4.13.	Transferring Profile-Forming Elements to Male Parts . . . . .	148
4.14.	Contour Milling . . . . .	148
4.15.	Chamfering of Form Surfaces . . . . .	150
4.16.	Machining of Sunk Surfaces . . . . .	151
4.17.	Machining of Bosses in Housings . . . . .	152
4.18.	Microgeometry of Frictional End Surfaces . . . . .	153
4.19.	Elimination of Unilateral Pressure on Cutting Tools . . . . .	153
4.20.	Elimination of Deformations Caused by Cutting Tools . . . . .	155
4.21.	Joint Machining of Parts of Different Hardness . . . . .	157
4.22.	Shockless Operation of Cutting Tools . . . . .	158
4.23.	Machining of Holes . . . . .	159
4.24.	Reduction of the Range of Cutting Tools . . . . .	161
4.25.	Centre Holes . . . . .	163
4.26.	Measurement Datum Surfaces . . . . .	165
4.27.	Increasing the Efficiency of Machining . . . . .	167
4.28.	Multiple Machining . . . . .	171
<b>Chapter 5.</b>	<b>Welded Joints . . . . .</b>	<b>174</b>
5.1.	Types of Welded Joints . . . . .	184
5.2.	Welds as Shown on Drawings . . . . .	186
5.3.	Drawings of Welded Joints . . . . .	196
5.4.	Design Rules . . . . .	199
5.5.	Increasing the Strength of Welded Joints . . . . .	199
5.6.	Joints Formed by Resistance Welding . . . . .	213
5.7.	Welding of Pipes . . . . .	215
5.8.	Welding-on of Flanges . . . . .	216
5.9.	Welding-on of Bushings . . . . .	217
5.10.	Welding-on of Bars . . . . .	219
5.11.	Welded Frames . . . . .	221
5.12.	Welded Truss Joints . . . . .	225
<b>Chapter 6.</b>	<b>Riveted Joints . . . . .</b>	<b>229</b>
6.1.	Hot Riveting . . . . .	229
6.2.	Cold Riveting . . . . .	231
6.3.	Rivet Materials . . . . .	233
6.4.	Types of Riveted Joints . . . . .	234
6.5.	Types of Rivets . . . . .	237
6.6.	Design Relative Proportions . . . . .	237
6.7.	Heading Allowances . . . . .	241
6.8.	Design Rules . . . . .	243
6.9.	Strengthening of Riveted Joints . . . . .	245
6.10.	Solid Rivets . . . . .	246
6.11.	Tubular Rivets . . . . .	247
6.12.	Thin-Walled Tubular Rivets . . . . .	249

6.13. Blind Rivets . . . . .	249
6.14. Special Rivets . . . . .	253
6.15. Riveting of Thin Sheets . . . . .	253
<b>Chapter 7. Fastening by Cold Plastic Deformation Methods . . . . .</b>	<b>255</b>
7.1. Fastening of Bushings . . . . .	256
7.2. Fastening of Bars . . . . .	256
7.3. Fastening of Axles and Pins . . . . .	258
7.4. Connection of Cylindrical Members . . . . .	259
7.5. Fastening of Parts on Surfaces . . . . .	260
7.6. Swaging Down of Annular Parts on Shafts . . . . .	261
7.7. Fastening of Plugs . . . . .	261
7.8. Fastening of Flanges to Pipes . . . . .	263
7.9. Fastening of Tubes . . . . .	263
7.10. Fastening by Means of Lugs . . . . .	264
7.11. Various Connections . . . . .	265
7.12. Seaming . . . . .	266
<b>Index . . . . .</b>	<b>269</b>



**B**ạn đang có trong tay thông tin cơ bản của một trong số những tài liệu có hàm lượng chất xám cao, với những thông tin vô cùng hữu ích cho quá trình học tập và nghiên cứu của bản thân bạn !

Bạn đã và đang trải qua những ưu tư, trăn trở của bản thân mình trước biến kiến thức mênh mông vô hạn và đang tìm hướng đi cho riêng mình bằng việc biến kiến thức thành tài sản tri thức của riêng bạn !

*Hãy đến Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM chia sẻ những khó khăn và trăn trở đó cùng bạn!*

*Hãy đến với Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cùng nhau, chúng ta xây dựng vương quốc khoa học và trí tuệ của chính mình !*



*Cùng với bạn, Thư viện ĐH Sư phạm Kỹ thuật Tp. HCM mong ước góp phần duy trì và phát triển văn hóa đọc !*




**Hãy đến với chúng tôi - Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM** để cảm nhận, trải nghiệm và biến ước mơ khoa học của bạn thành hiện thực !

Hân hạnh được đón tiếp và phục vụ bạn tại  
**Số 1 – 3, Võ Văn Ngân, Phường Linh Chiểu, Quận Thủ Đức, Tp. HCM**  
ĐT: (08) 3896 9920 – Email: [thuvienspkt@hcmute.edu.vn](mailto:thuvienspkt@hcmute.edu.vn)  
<http://www.thuvienspkt.edu.vn> – <http://thuvien.hcmute.edu.vn>



## ***Thông tin tài trợ!***





**B**ạn đang có trong tay thông tin cơ bản của một trong số những tài liệu có hàm lượng chất xám cao, với những thông tin vô cùng hữu ích cho quá trình học tập và nghiên cứu của bản thân bạn !

Bạn đã và đang trải qua những ưu tư, trăn trở của bản thân mình trước biển kiến thức mênh mông vô hạn và đang tìm hướng đi cho riêng mình bằng việc biến kiến thức thành tài sản tri thức của riêng bạn !

*Hãy đến Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM chia sẻ những khó khăn và trăn trở đó cùng bạn!*

*Hãy đến với Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cùng nhau, chúng ta xây dựng vương quốc khoa học và trí tuệ của chính mình !*



*Cùng với bạn, Thư viện ĐH Sư phạm Kỹ thuật Tp. HCM mong ước góp phần duy trì và phát triển văn hóa đọc !*



**Hãy đến với chúng tôi - Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM** để cảm nhận, trải nghiệm và biến ước mơ khoa học của bạn thành hiện thực !

Hân hạnh được đón tiếp và phục vụ bạn tại  
**Số 1 – 3, Võ Văn Ngân, Phường Linh Chiểu, Quận Thủ Đức, Tp. HCM**  
ĐT: (08) 3896 9920 – Email: [thuvienspkt@hcmute.edu.vn](mailto:thuvienspkt@hcmute.edu.vn)  
<http://www.thuvienspkt.edu.vn> – <http://thuvien.hcmute.edu.vn>



## **Thông tin tài trợ!**

