


# TECHNOLOGY OF MACHINE TOOLS


FIFTH EDITION



Steve F. Krar  
Albert F. Check

# TECHNOLOGY OF MACHINE TOOLS

FIFTH EDITION



**Steve F. Krar**  
**Albert F. Check**

THƯ VIỆN TRƯỜNG ĐHSPT

SKN 006505

**GLENCOE**

McGraw-Hill

New York, New York   Columbus, Ohio   Woodland Hills, California   Peoria, Illinois

# C O N T E N T S

<b>Preface</b>	<b>vii</b>
<b>About the Authors</b>	<b>viii</b>
<b>Acknowledgments</b>	<b>ix</b>

## Section

### **1 Introduction to Machine Tools** **2**

<b>Unit 1</b> History of Machines	<b>4</b>
-----------------------------------	----------

## Section

### **2 Machine Trade Opportunities** **16**

<b>Unit 2</b> Careers in the Metalworking Industry	<b>18</b>
<b>Unit 3</b> Getting the Job	<b>27</b>

## Section

### **3 Safety** **32**

<b>Unit 4</b> Safety in the Machine Shop	<b>34</b>
--	-----------

## Section

### **4 Job Planning** **40**

<b>Unit 5</b> Engineering Drawings	<b>42</b>
<b>Unit 6</b> Machining Procedures for Various Workpieces	<b>47</b>

## Section

### **5 Measurement** **54**

<b>Unit 7</b> Basic Measurement	<b>58</b>
<b>Unit 8</b> Squares and Surface Plates	<b>64</b>
<b>Unit 9</b> Micrometers - Precision Measuring Tools (Units 9-18)	<b>69</b>
<b>Unit 10</b> Vernier Calipers	<b>78</b>
<b>Unit 11</b> Inside-, Depth-, and Height-Measuring Instruments	<b>83</b>
<b>Unit 12</b> Gage Blocks	<b>93</b>
<b>Unit 13</b> Angular Measurement	<b>98</b>
<b>Unit 14</b> Gages	<b>104</b>
<b>Unit 15</b> Comparison Measurement	<b>111</b>
<b>Unit 16</b> The Coordinate Measuring System	<b>121</b>
<b>Unit 17</b> Measuring with Light Waves	<b>126</b>
<b>Unit 18</b> Surface Finish Measurement	<b>131</b>

## Section

### **6 Layout Tools and Procedures** **136**

<b>Unit 19</b> Basic Layout Materials, Tools, and Accessories	<b>138</b>
<b>Unit 20</b> Basic or Semiprecision Layout	<b>146</b>
<b>Unit 21</b> Precision Layout	<b>150</b>

**Section****7****Hand Tools and Bench Work****156**

<b>Unit 22</b>	Holding, Striking, and Assembling Tools	<b>158</b>
<b>Unit 23</b>	Hand-Type Cutting Tools	<b>164</b>
<b>Unit 24</b>	Thread-Cutting Tools and Procedures	<b>171</b>
<b>Unit 25</b>	Finishing Processes—Reaming, Broaching, and Lapping	<b>177</b>
<b>Unit 26</b>	Bearings	<b>184</b>

**Section****8****Metal-Cutting Technology****188**

<b>Unit 27</b>	Physics of Metal Cutting	<b>190</b>
<b>Unit 28</b>	Machinability of Metals	<b>196</b>
<b>Unit 29</b>	Cutting Tools	<b>201</b>
<b>Unit 30</b>	Operating Conditions and Tool Life	<b>212</b>
<b>Unit 31</b>	Carbide Cutting Tools	<b>216</b>
<b>Unit 32</b>	Diamond, Ceramic, and Cermet Cutting Tools	<b>234</b>
<b>Unit 33</b>	Polycrystalline Cutting Tools	<b>244</b>
<b>Unit 34</b>	Cutting Fluids—Types and Applications	<b>252</b>

**Section****9****Metal-Cutting Saws****262**

<b>Unit 35</b>	Types of Metal Saws	<b>264</b>
<b>Unit 36</b>	Contour Bandsaw Parts and Accessories	<b>269</b>
<b>Unit 37</b>	Contour Bandsaw Operations	<b>276</b>

**Section****10****Drilling Machines****286**

<b>Unit 38</b>	Drill Presses	<b>288</b>
<b>Unit 39</b>	Drilling Machine Accessories	<b>294</b>
<b>Unit 40</b>	Twist Drills	<b>300</b>
<b>Unit 41</b>	Cutting Speeds and Feeds	<b>309</b>
<b>Unit 42</b>	Drilling Holes	<b>313</b>
<b>Unit 43</b>	Reaming	<b>321</b>
<b>Unit 44</b>	Drill Press Operations	<b>328</b>

**Section****11****The Lathe****334**

<b>Unit 45</b>	Engine Lathe Parts	<b>339</b>
<b>Unit 46</b>	Lathe Accessories	<b>344</b>
<b>Unit 47</b>	Cutting Speed, Feed, and Depth of Cut	<b>356</b>
<b>Unit 48</b>	Lathe Safety	<b>361</b>
<b>Unit 49</b>	Mounting, Removing, and Aligning Lathe Centers	<b>364</b>
<b>Unit 50</b>	Grinding Lathe Cutting Tools	<b>368</b>
<b>Unit 51</b>	Facing Between Centers	<b>371</b>
<b>Unit 52</b>	Machining Between Centers	<b>376</b>
<b>Unit 53</b>	Knurling, Grooving, and Form Turning	<b>384</b>
<b>Unit 54</b>	Tapers and Taper Turning	<b>391</b>
<b>Unit 55</b>	Threads and Thread Cutting	<b>402</b>
<b>Unit 56</b>	Steady Rests, Follower Rests, and Mandrels	<b>422</b>
<b>Unit 57</b>	Machining in a Chuck	<b>428</b>
<b>Unit 58</b>	Drilling, Boring, Reaming, and Tapping	<b>440</b>

**Section**

---

**12 Milling Machines 446**

<b>Unit 59</b> Milling Machines and Accessories	<b>448</b>
<b>Unit 60</b> Milling Cutters	<b>458</b>
<b>Unit 61</b> Cutting Speed, Feed, and Depth of Cut	<b>465</b>
<b>Unit 62</b> Milling Machine Setups	<b>474</b>
<b>Unit 63</b> Milling Operations	<b>481</b>
<b>Unit 64</b> The Indexing or Dividing Head	<b>488</b>
<b>Unit 65</b> Gears	<b>497</b>
<b>Unit 66</b> Gear Cutting	<b>504</b>
<b>Unit 67</b> Helical Milling	<b>511</b>
<b>Unit 68</b> Cam, Rack, Worm, and Clutch Milling	<b>518</b>
<b>Unit 69</b> The Vertical Milling Machine— Construction and Operation	<b>527</b>
<b>Unit 70</b> Special Milling Operations	<b>544</b>

**Section**

---

**13 The Jig Borer and Jig Grinder 552**

<b>Unit 71</b> The Jig Borer	<b>554</b>
<b>Unit 72</b> Jig-Boring Holes	<b>560</b>
<b>Unit 73</b> The Jig Grinder	<b>570</b>

**Section**

---

**14 Computer-Age Machining 580**

<b>Unit 74</b> The Computer	<b>582</b>
<b>Unit 75</b> Computer Numerical Control	<b>585</b>

<b>Unit 76</b> CNC Turning Center	<b>604</b>
<b>Unit 77</b> CNC Machining Centers	<b>625</b>
<b>Unit 78</b> Computer-Aided Design	<b>643</b>
<b>Unit 79</b> Robotics	<b>647</b>
<b>Unit 80</b> Manufacturing Systems	<b>654</b>
<b>Unit 81</b> Factories of the Future	<b>659</b>

**Section**

---

**15 Grinding 664**

<b>Unit 82</b> Types of Abrasives	<b>666</b>
<b>Unit 83</b> Surface Grinders and Accessories	<b>686</b>
<b>Unit 84</b> Surface-Grinding Operations	<b>698</b>
<b>Unit 85</b> Cylindrical Grinders	<b>711</b>
<b>Unit 86</b> Universal Cutter and Tool Grinder	<b>721</b>

**Section**

---

**16 Metallurgy 734**

<b>Unit 87</b> Manufacture and Properties of Steel	<b>736</b>
<b>Unit 88</b> Heat Treatment of Steel	<b>750</b>
<b>Unit 89</b> Testing of Metals and Nonferrous Metals	<b>765</b>

**Section**

---

**17 Hydraulics 776**

<b>Unit 90</b> Hydraulic Circuits and Components	<b>778</b>
--	------------

**Section****18****Special Processes****788**

<b>Unit 91</b> Electro-Chemical Machining and Electrolytic Grinding	<b>790</b>
<b>Unit 92</b> Electrical Discharge Machining	<b>797</b>
<b>Unit 93</b> Forming Processes	<b>807</b>
<b>Unit 94</b> The Laser	<b>816</b>

**Section****19****Glossary  
Appendices  
Index****819**

<b>Glossary</b>	<b>820</b>
<b>Appendix of Tables</b>	<b>831</b>
<b>Table 1</b> - Decimal Inch, Fractional Inch, and Millimeter Equivalents	<b>831</b>
<b>Table 2</b> - Conversion of Inches to Millimeters Conversion of Millimeters to Inches	<b>831</b>
<b>Table 3</b> - Letter Drill Sizes	<b>831</b>
<b>Table 4</b> - Drill Gage Sizes	<b>832</b>
<b>Table 5</b> - Tap Drill Sizes	<b>832</b>
<b>Table 6</b> - Isometric Pitch and Diameter Combinations	<b>832</b>
<b>Table 7</b> - Tap Drill Sizes	<b>833</b>
<b>Table 8</b> - Three Wire Thread Measurement (60°)	<b>833</b>
<b>Table 9</b> - Commonly Used Formulas	<b>833</b>
<b>Table 10</b> - Formula Shortcuts	<b>834</b>
<b>Table 11</b> - Morse Tapers	<b>834</b>
<b>Table 12</b> - Standard Milling Machine Taper	<b>835</b>
<b>Table 13</b> - Tapers and Angles	<b>835</b>
<b>Table 14</b> - Allowances for Fits	<b>836</b>
<b>Table 15</b> - Rules for Finding Dimensions of Circles, Squares, Etc.	<b>836</b>

<b>Table 16</b> - Hardness Conversion Chart	<b>837</b>
---	------------

<b>Table 17</b> - Solutions for Right-Angled Triangles	<b>838</b>
--	------------

<b>Table 18</b> - Tool Steel Types	<b>838</b>
------------------------------------	------------

<b>Table 19</b> - Sine Bar Constants ( 5 in. Bar)	<b>841</b>
---	------------

<b>Table 20</b> - Coordinate Factors and Angles	
20A ( 3-Hole Division)	<b>844</b>
20B ( 4-Hole Division)	<b>844</b>
20C ( 5-Hole Division)	<b>844</b>
20D ( 6-Hole Division)	<b>845</b>
20E ( 7-Hole Division)	<b>845</b>
20F ( 8-Hole Division)	<b>845</b>
20G ( 9-Hole Division)	<b>846</b>
20H (10-Hole Division)	<b>846</b>
20I (11-Hole Division)	<b>846</b>

<b>Table 21</b> Natural Trigonometric Functions	<b>847</b>
---	------------

<b>Index</b>	<b>859</b>
--------------	------------

**B**ạn đang có trong tay thông tin cơ bản của một trong số những tài liệu có hàm lượng chất xám cao, với những thông tin vô cùng hữu ích cho quá trình học tập và nghiên cứu của bản thân bạn !

Bạn đã và đang trải qua những ưu tư, trăn trở của bản thân mình trước biển kiến thức mênh mông vô hạn và đang tìm hướng đi cho riêng mình bằng việc biến kiến thức thành tài sản tri thức của riêng bạn !

*Hãy để Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM chia sẻ những khó khăn và trăn trở đó cùng bạn!*

*Hãy đến với Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cùng nhau, chúng ta xây dựng vương quốc khoa học và trí tuệ của chính mình !*

*Cùng với bạn, Thư viện ĐH Sư phạm Kỹ thuật Tp. HCM mong ước góp phần duy trì và phát triển văn hóa đọc !*



**Hãy đến với chúng tôi - Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM** để cảm nhận, trải nghiệm và biến ước mơ khoa học của bạn thành hiện thực !

Hân hạnh được đón tiếp và phục vụ bạn tại  
**Số 1 – 3, Võ Văn Ngân, Phường Linh Chiểu, Quận Thủ Đức, Tp. HCM**  
ĐT: (08) 3896 9920 – Email: [thuvienspkt@hcmute.edu.vn](mailto:thuvienspkt@hcmute.edu.vn)  
<http://www.thuvienspkt.edu.vn> – <http://thuvien.hcmute.edu.vn>

***Thông tin tài trợ!***



A series of horizontal dotted lines spanning the width of the page, providing a template for writing. There are 18 lines in total, arranged in a central column.



**B**ạn đang có trong tay thông tin cơ bản của một trong số những tài liệu có hàm lượng chất xám cao, với những thông tin vô cùng hữu ích cho quá trình học tập và nghiên cứu của bản thân bạn !

Bạn đã và đang trải qua những ưu tư, trăn trở của bản thân mình trước biển kiến thức mênh mông vô hạn và đang tìm hướng đi cho riêng mình bằng việc biến kiến thức thành tài sản tri thức của riêng bạn !

*Hãy để Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM chia sẻ những khó khăn và trăn trở đó cùng bạn!*

*Hãy đến với Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cùng nhau, chúng ta xây dựng vương quốc khoa học và trí tuệ của chính mình !*

*Cùng với bạn, Thư viện ĐH Sư phạm Kỹ thuật Tp. HCM mong ước góp phần duy trì và phát triển văn hóa đọc !*



**Hãy đến với chúng tôi - Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM** để cảm nhận, trải nghiệm và biến ước mơ khoa học của bạn thành hiện thực !

Hân hạnh được đón tiếp và phục vụ bạn tại  
**Số 1 – 3, Võ Văn Ngân, Phường Linh Chiểu, Quận Thủ Đức, Tp. HCM**  
ĐT: (08) 3896 9920 – Email: [thuvienspkt@hcmute.edu.vn](mailto:thuvienspkt@hcmute.edu.vn)  
<http://www.thuvienspkt.edu.vn> – <http://thuvien.hcmute.edu.vn>

***Thông tin tài trợ!***



A series of horizontal dotted lines spanning the width of the page, intended for handwritten text. There are 15 lines in total, providing a structured space for the donor information.

