


INTERNATIONAL EDITION

Design of
MACHINE ELEMENTS
EIGHTH EDITION



M. F. SPOTTS ■ T. E. SHOUP
L. E. HORNBERGER

Design of Machine Elements

Eighth Edition

M. F. Spotts


*Late, Professor Emeritus
of Mechanical Engineering Department
Northwestern University*

T. E. Shoup

*Department of Mechanical Engineering
Santa Clara University*

L. E. Hornberger

*Department of Mechanical Engineering
Santa Clara University*



Pearson Education International

THƯ VIỆN TRƯỜNG ĐHSPT

SKV 004206



Contents

PREFACE

xv

INTRODUCTION

1

I-1	Problem Solving and Design	1
I-2	The Design Process	3
I-3	Stages of Design	5
I-4	Finding and Using Information in Machine Design	7
I-5	Recognized Standards for Design	9
I-6	Computational Tools for Machine Design	11
I-7	Conclusions	14
	References	14

CHAPTER 1 FUNDAMENTAL PRINCIPLES 15

1-1	Statical Equilibrium	17
1-2	Engineering Materials	17
1-3	Tension and Compression Stress	18
1-4	Tension and Compression in SI Units	20
1-5	Force and Mass	22

1-6	Statically Indeterminate Problems in Tension and Compression	23
1-7	Center of Gravity	25
1-8	Bending of Beams	27
1-9	Moment of Inertia	30
1-10	Transfer Axis for Moment of Inertia	33
1-11	Principle of Superposition	35
1-12	Additional Beam Equations	38
1-13	Deflection of Beams	39
1-14	Effect of Ribs on Castings	46
1-15	Shearing Stress	48
1-16	Transverse Shearing Stress in Beams	49
1-17	Shear and Bending Moment Diagrams	55
1-18	Slender Compression Members or Columns	58
1-19	Stresses in Any Given Direction	62
1-20	The Mohr Circle	64
1-21	Stress Manipulation in Three Dimensions	68
1-22	Stresses and Deformations in Two Directions	76
1-23	Deflection of A Beam from Shearing Stress	77
1-24	Principle of St. Venant	79
	References	80
	Problems	80
CHAPTER 2 WORKING STRESSES AND FAILURE THEORIES		119
2-1	Failure and Phenomenological Failure Theories	120
2-2	Stress-Strain Diagrams	123
2-3	Phenomenological Failure Theories Based on Stress	126
2-4	Stress Concentration Caused by Sudden Change in Form	137
2-5	Design for Cyclic Loading	151
2-6	Conclusion	168
	References	169
	Problems	170

CHAPTER 3 DESIGN OF SHAFTS 185

3-1	Torsion of Circular Shaft	187
3-2	Power Transmitted	194
3-3	Maximum Static Shearing Stress	197
3-4	Design of Shafts for Fluctuating Loads	198
3-5	Keys	204
3-6	Stress Concentration	208
3-7	Couplings	210
3-8	Bending Loads in Two Planes	213
3-9	Shaft on Three Supports	213
3-10	Crankshafts	217
3-11	Critical Speed of a Rotating Shaft	220
3-12	Deflection of Shaft of Nonuniform Diameter	221
3-13	Slope of Shaft by Elastic Energy	224
3-14	Torsion of Noncircular Shafts	225
3-15	Torsion of a Wide Rectangular Bar	226
3-16	Torsion of Rectangular Bars—General Case	228
3-17	Composite Sections	230
3-18	Thin-Walled Tube	233
3-19	Materials Used for Shafting	235
	References	236
	Problems	237

CHAPTER 4 SPRINGS 261

4-1	Helical Springs	263
4-2	Properties of Spring Materials	268
4-3	Hot-Formed Springs	270
4-4	Helical Spring of Minimum Volume of Material—Static Load	271
4-5	Optimum Design of Helical Spring	275
4-6	Fatigue of Springs	280

4-7	Design for Fluctuating Loads	281
4-8	Buckling of Compression Springs	284
4-9	Vibration or Surging of Helical Springs	284
4-10	Commercial Tolerances	285
4-11	Effect of End Turns for Compression Springs	287
4-12	Helical Extension Springs	288
4-13	Helical Springs of Rectangular Wire	289
4-14	Helical Springs with Torsional Loading	291
4-15	Leaf Springs	294
4-16	Energy Storage by Springs	298
4-17	Belleville Spring	299
4-18	Rubber Springs	301
	References	308
	Problems	308

CHAPTER 5 SCREWS 316

5-1	Kinds of Threads	316
5-2	Standardized Threads	319
5-3	Unified Threads	321
5-4	American National Threads	322
5-5	Identification Symbols	323
5-6	SI Threads	323
5-7	Effect of Initial Stress	325
5-8	Additional Design Considerations	329
5-9	Power Screws	331
5-10	Torque Required to Produce Desired Clamping Force	339
5-11	Friction of Screws	341
5-12	Stress Concentration	341
5-13	Locknuts	343
5-14	Materials and Methods of Manufacture	344
5-15	Stress Due to Impact Load	345

5-16	Relaxation	348	
	References	348	
	Problems	348	
CHAPTER 6	BELTS, CLUTCHES, BRAKES AND CHAINS		354
6-1	V-belts	355	
6-2	Center Distance for V-belt Drive	357	
6-3	Design of V-belts	361	
6-4	Other Types of Belts	363	
6-5	Disk or Plate Clutch	365	
6-6	Disk Brakes	369	
6-7	Cone Clutch	370	
6-8	Band Brake	371	
6-9	Block Brake with Short Shoe	375	
6-10	Pivoted Block Brake with Long Shoe	376	
6-11	Brake with Pivoted Symmetrical Shoe	385	
6-12	Lining Pressures	386	
6-13	Heating of Brakes	387	
6-14	Roller Chains	388	
6-15	Design Capacity of Roller Chains	389	
6-16	Galling of Roller Chains	393	
6-17	Polygonal Action	394	
6-18	Silent Chain	395	
	References	396	
	Problems	396	
CHAPTER 7	WELDED AND RIVETED CONNECTIONS		408
7-1	Fabrication by Welding	409	
7-2	Fusion Welding	410	
7-3	Strength of Fusion Welds	411	
7-4	Eccentrically Loaded Welds—Static Loads	413	

7-5	Stress Concentration in Welds	420
7-6	Residual Stress—Weldability	421
7-7	Welding Electrodes	423
7-8	Design for Fluctuating Loads	424
7-9	Resistance Welding	426
7-10	Other Kinds of Welding	427
7-11	Soldering and Brazing	429
7-12	Furnace Brazing	431
7-13	Riveted Joint with Central Load	432
7-14	Stresses in Rivets	433
7-15	Stresses in a Cylindrical Shell	433
7-16	Riveted Joint with Eccentric Load	437
7-17	Instantaneous Center of Rotation	442
7-18	Adhesives	442
	References	444
	Problems	445
CHAPTER 8	<i>LUBRICATION</i>	456
8-1	Viscosity and Newton's Law	458
8-2	Petroff's Bearing Equation	466
8-3	Load-Carrying Journal Bearing	470
8-4	Load and Friction Curves for Journal Bearings	471
8-5	Power Lost in Friction	478
8-6	Power Lost by Self-Cooled Bearings	479
8-7	Designing for Film Temperature and Minimum Film Thickness	484
8-8	Viscosity Index	486
8-9	The <i>Zn/P</i> Curve	487
8-10	Bearing Materials	490
8-11	Bearing Loads	493
8-12	Construction of Bearings	494

8-13	Clearance and Oil Grooves	495
8-14	Elastic Matching	497
8-15	Dry Friction	498
8-16	Boundary or Thin-Film Lubrication	499
8-17	Mixed or Semifluid Lubrication	500
	References	500
	Problems	501
CHAPTER 9	BALL AND ROLLER BEARINGS	506
9-1	Construction and Types of Ball Bearings	506
9-2	Selection of Ball Bearings	508
9-3	Effect of Axial Load	512
9-4	Design for Variable Loading	515
9-5	Static Capacity	519
9-6	Design for Different Confidence Levels	520
9-7	Friction and Lubrication of Ball Bearings	520
9-8	Bearing Materials and Surface Finish	521
9-9	Mounting of Ball Bearings	522
9-10	Permissible Misalignment	524
9-11	Unground Ball Bearings	525
9-12	Relative Advantages of Rolling Element Bearings	525
9-13	Roller Bearings	526
9-14	Contact Stress between Spheres and Cylinders	528
9-15	Elasto-hydrodynamic Lubrication	537
	References	537
	Problems	538
CHAPTER 10	SPUR GEARS	543
10-1	Introduction	545
10-2	Velocity Law of Toothed Gearing	546
10-3	Kinematics of Involute Gear Teeth	548

10-4	Cycloidal Gear Teeth	550	
10-5	Pitches of Gear Teeth	551	
10-6	Gear Pitches in SI Units	554	
10-7	Standard Systems of Gearing	557	
10-8	Methods of Manufacture	559	
10-9	Backlash	562	
10-10	Gear Finishing Methods	564	
10-11	Load on Gear Tooth from Power Transmitted		564
10-12	Determination of Bearing Loads	567	
10-13	Contact Ratio	569	
10-14	Undercutting in Gear Teeth	571	
10-15	Long and Short Addendum Gearing		573
10-16	Speed Ratios of Gear Trains	576	
10-17	Internal or Annular Gears	580	
10-18	Dimensioning of Gears	581	
10-19	Materials for Gears	581	
10-20	Lubrication and Mounting of Gears		582
10-21	Planetary Gear Trains	583	
10-22	Design of Gears to Prevent Failures		585
	References	617	
	Problems	618	
CHAPTER 11 HELICAL, BEVEL, AND WORM GEARS			626
11-1	Helical Gears	627	
11-2	The Geometry of Helical Gears		630
11-3	Virtual Number of Teeth	632	
11-4	Center Distance of Mating Gears		632
11-5	Contact Ratios for Helical Gears		635
11-6	Tooth Loads of Helical Gears		635
11-7	Design of Parallel Shaft Helical Gears to Prevent Failures		636

11-8	Bevel Gears	651	
11-9	The Geometry of Bevel Gears	653	
11-10	Loads on Bevel Gears	654	
11-11	Design of Bevel Gears to Prevent Failures	655	
11-12	Worm Gears	666	
11-13	Geometric Relationships of Worm Gears	668	
11-14	Forces in Worm Gear Sets	676	
11-15	Design of Worm Gear Sets	676	
	References	681	
	Problems	681	
CHAPTER 12 MISCELLANEOUS MACHINE ELEMENTS			684
12-1	Stresses in a Thick Cylinder	684	
12-2	Shrink and Press Fit Stresses	689	
12-3	Stress Concentration Caused by Press Fit	693	
12-4	Stresses in Disk Flywheel	698	
12-5	Flywheel with Spokes and Rim	700	
12-6	Flywheel Requirements	704	
12-7	Impact of Elastic Bodies	707	
12-8	Impact Stresses by Energy Method	709	
12-9	Force Produced by Falling Weight	715	
12-10	Impact of Weight on Beam	717	
12-11	Gaskets and Seals	718	
12-12	Design of Gaskets for Static Loads	720	
12-13	Wire Rope	724	
12-14	Curved Beams	729	
12-15	Curved Beam of Rectangular Cross Section	732	
12-16	Curved Beam of Circular Cross Section	737	
12-17	Angular Deflection of Curved Bar	737	
12-18	Cams	737	
12-19	Plate Cam with Central Roller Follower	740	

12-20	Manufacture of Cam with Central Roller Follower	742
12-21	Plate Cam with Flat-Faced Follower	744
12-22	Polydyne Cam	746
12-23	Remarks on Cam Design	746
12-24	Snap Rings	747
12-25	Flat Plates	748
	References	752
	Problems	753
CHAPTER 13 PRINCIPLES OF FORM SYNTHESIS		763
13-1	A Review of Stress Patterns in Machine Parts	763
13-2	The Principles of Form Synthesis	767
13-3	Exceptions to the Form Synthesis Principles	769
13-4	Design of Joints	770
13-5	Conclusions	777
	References	778
	Problems	778
CHAPTER 14 ENGINEERING MATERIALS		780
14-1	The Tension Test	780
14-2	Physical Constitution of Steel	783
14-3	Types of Steel Used in Machine Construction	785
14-4	Numbering Systems for Carbon and Alloy Steels	786
14-5	Plain Carbon Steel	789
14-6	Alloy Steels	793
14-7	High-Strength Low-Alloy Steels, HSLA	798
14-8	Cost of Steel	798
14-9	Heat Treatment of Steel	799
14-10	Residual Stresses from Heat Treatment	802
14-11	Carburizing and Nitriding	803

14-12	Flame Hardening	804
14-13	Strain Hardening	806
14-14	Hardness	807
14-15	Machinability	809
14-16	Grain Size	809
14-17	Corrosion	810
14-18	Prevention of Corrosion	811
14-19	Stainless Steel	812
14-20	Wear	813
14-21	Short-Term Effects of High Temperatures	816
14-22	Creep of Steel at High Temperature	817
14-23	Cast Iron	819
14-24	Malleable Iron/Nodular Iron	822
14-25	Cast Steel	822
14-26	Tool Steel	824
14-27	Aluminum Alloys	825
14-28	Alloy and Temper Designations	826
14-29	Composition and Mechanical Properties	827
14-30	Magnesium Alloys	827
14-31	Copper Alloys	830
14-32	Alloys for Die Castings	833
	References	836
CHAPTER 15 DESIGNING WITH PLASTIC MATERIALS		837
15-1	Introduction	837
15-2	The Basics: The Chemistry and Physics of Plastics	841
15-3	Characteristics of Thermoplastic Materials	842
15-4	Amorphous vs. Semicrystalline Thermoplastics	844
15-5	Characteristics of Thermoset Materials	847
15-6	Designing with Plastics	850

15-7	Creep in Plastics	850
15-8	Environmental Properties of Plastics	855
15-9	Safety Factors	856
15-10	Additives for Plastics	856
15-11	Recycling of Plastics	857
15-12	Plastics Resources	857
	References	857
	Problems	858
<i>APPENDIX</i>	<i>MODULES</i>	<i>860</i>
<i>INDEX</i>	<i>914</i>	

Bạn đang có trong tay thông tin cơ bản của một trong số những tài liệu có hàm lượng chất xám cao, với những thông tin vô cùng hữu ích cho quá trình học tập và nghiên cứu của bản thân bạn !

Bạn đã và đang trải qua những ưu tư, trăn trở của bản thân mình trước biển kiến thức mênh mông vô hạn và đang tìm hướng đi cho riêng mình bằng việc biến kiến thức thành tài sản tri thức của riêng bạn !

Hãy để Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM chia sẻ những khó khăn và trăn trở đó cùng bạn!

Hãy đến với Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cùng nhau, chúng ta xây dựng vương quốc khoa học và trí tuệ của chính mình !

Cùng với bạn, Thư viện ĐH Sư phạm Kỹ thuật Tp. HCM mong ước góp phần duy trì và phát triển văn hóa đọc !



Hãy đến với chúng tôi - Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cảm nhận, trải nghiệm và biến ước mơ khoa học của bạn thành hiện thực !

Hân hạnh được đón tiếp và phục vụ bạn tại
Số 1 – 3, Võ Văn Ngân, Phường Linh Chiểu, Quận Thủ Đức, Tp. HCM
ĐT: (08) 3896 9920 – Email: thuvienspkt@hcmute.edu.vn
<http://www.thuvienspkt.edu.vn> – <http://thuvien.hcmute.edu.vn>

Thông tin tài trợ!



A series of horizontal dotted lines spanning the width of the page, intended for handwritten text. There are 18 lines in total, providing a structured space for the donor information.



Bạn đang có trong tay thông tin cơ bản của một trong số những tài liệu có hàm lượng chất xám cao, với những thông tin vô cùng hữu ích cho quá trình học tập và nghiên cứu của bản thân bạn !

Bạn đã và đang trải qua những ưu tư, trăn trở của bản thân mình trước biển kiến thức mênh mông vô hạn và đang tìm hướng đi cho riêng mình bằng việc biến kiến thức thành tài sản tri thức của riêng bạn !

Hãy để Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM chia sẻ những khó khăn và trăn trở đó cùng bạn!

Hãy đến với Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cùng nhau, chúng ta xây dựng vương quốc khoa học và trí tuệ của chính mình !

Cùng với bạn, Thư viện ĐH Sư phạm Kỹ thuật Tp. HCM mong ước góp phần duy trì và phát triển văn hóa đọc !



Hãy đến với chúng tôi - Thư viện trường Đại học Sư phạm Kỹ thuật Tp. HCM để cảm nhận, trải nghiệm và biến ước mơ khoa học của bạn thành hiện thực !

Hân hạnh được đón tiếp và phục vụ bạn tại
Số 1 – 3, Võ Văn Ngân, Phường Linh Chiểu, Quận Thủ Đức, Tp. HCM
ĐT: (08) 3896 9920 – Email: thuvienspkt@hcmute.edu.vn
<http://www.thuvienspkt.edu.vn> – <http://thuvien.hcmute.edu.vn>

Thông tin tài trợ!



A series of horizontal dotted lines for writing, arranged in a central column. There are 18 lines in total, providing space for a message or acknowledgment.

